



DJI\_20221217135929\_0014\_T.JPG

2022/12/17 13:59:29

|Measurements

SQ1	MIN	-8.9°C
	AVERAGE	-6.3°C
	MAX	-3.6°C
SQ2	MIN	-9.4°C
	AVERAGE	-8.6°C
	MAX	-7.8°C
SQ3	MIN	-9.1°C
	AVERAGE	-8.2°C
	MAX	-7.2°C

SQ4	MIN	-8.9°C
	AVERAGE	-7.5°C
	MAX	-6.1°C
SQ5	MIN	-9.4°C
	AVERAGE	-8.3°C
	MAX	-7.3°C

#### |Parameters

Distance	5 m
Humidity	50%
Emissivity	0.95
Reflected Temp	25.0°C

#### |Image Info

Model	M3T
Serial Number	1581F5FJB22A700A0ES
Focal Length	9.1 mm
Aperture	f/1.0
Width	640
Height	512
Created	2022/12/17 13:59:29
Modified	2023/01/02 00:28:20

#### |Remarks

Disturbed/damaged asphalt creating hotspot. SQ1 shows -3.6C, which is on average 3.5C warmer than the SQ2-5. The hot spot could indicate roof damage and a point of penetration.